

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Shyju T.K
Sriajul Hudu English Medium School
Kuttiadi
6.18 x 6.18 x 3.63 (2nd) 5.96 x 6.18 x 3.63 (1st) } G
6.18 x 6.18 x 3.63 (4th) 5.96 x 6.18 x 3.63 (2nd) } FF
6.18 x 6.23 x 3.63 (1st) 6.09 x 6.17 x 3.63 (1st) }
6.18 x 6.18 x 3.63 (4th) 6.18 x 6.23 x 3.63 (1st) } SF
5.96 x 6.18 x 3.63 (2nd) 6.09 x 6.17 x 3.63 (1st) }

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

2024-2025
Nil
Nil
Yes

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 03.01.2025 and found to be fit / unfit to conduct classes, for the period 2024-25 for the reasons stated above. (under normal wind and weather condition)

Place: Vaboli

Date: 03.01.2025

PRINCIPAL

500/8-6-13 SIRAJUL HUDA ENGLISH MEDIUM SCHOOL



[Signature]

-Assistant Engineer

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

R. K. S. Smith S
Sirajul Huda English medium School
Kuttiadi - Vadakara - Kunnammal
concrete building - RCC roof
(1) 12.57 x 6.18 x 3.60, 4.13 x 6.18 x 3.60 (2 nos) GF
(2) 9.33 x 6.18 x 3.60, 6.16 x 6.18 x 3.60 (3 Nos)
(3) 6.16 x 6.18 x 3.60 (2 nos), 6.16 x 6.18 x 3.60 (3 nos) FF
(4) 6.25 x 6.18 x 3.60 (4 nos) x 6.25 x 4.13 x 3.60 (1 no)
(5) 6.25 x 4.13 x 3.60 (1 no) SF
2024-25

Period for which the certificate is issued

Nature of Defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Any major defects noticed which will render the building unsafe in any manner

No defects

Whether maintenance works have been done properly

Yes

Whether the structure is sound or not for conducting classes

Sound enough to conduct class under weather condition.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, normal exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 7-10-2024 and found to be fit / unfit to conduct classes, for the period 2024-25 for the reasons stated above.

Place: Layalodu

Date: 7-10-2024



[Signature]
Assistant Engineer